

Gaussmeter Probes for FH 41, FH 42, FH 43

Model Number	Description	Item Number
FH-43 Probes		
STD58-0404	4" Transverse Probe (Std. w. meter)	125804
STD58-0402	2" Transverse Probe	125803
SAD58-1904	4" Axial Probe	125802
SAD58-1902	2" Axial Probe	125801
FH-42 Probes		
STH57-0404	4" Transverse Probe (Std. w. meter)	125704
STH57-0402	2" Transverse Probe	125703
SAH57-1904	4" Axial Probe	125702
SAH57-1902	2" Axial Probe	125701
FH-41 Probes		
HTV56-0602	2" H.D. Transverse Probe (Std. w. meter)	125605
STV56-0404	4" Transverse Probe	125604
STV56-0402	2" Transverse Probe	125603
SAV56-1904	4" Axial Probe	125602
SAV56-1902	2" Axial Probe	125601
Meter Accessories		
X-5000-0006	6 ft. Extension Cable	125000
YA-111	Zero Gauss chamber (Std. w. meter)	122920
PSU-15	AC Adapter, 110V	145012
PSR-15	AC Adapter, Switching	115001